

# SCIENCE INSTRUMENT AIRWORTHINESS AND CERTIFICATION PROCEDURES MANUAL

## Appendix II: Resources

This appendix will be a resource for SI builders and designers for parts, materials, wire, and any other certified items that will be required. This is not intended to be a complete listing, but a place to begin. As more information becomes available, this list will be updated. Additionally, any SI team may add to this list if another unlisted resource is available.

### **Aircraft Modification Companies**

The following partial list is for help in modifying non-certified equipment so that it can be certified. ATS has done cryocooler certification, for example.

Aircraft Technical Services (ATS)

818-786-5341

16543 Arminta, St.

Van Nuys, Ca. 91406

### **Aircraft Suppliers**

#### **Aircraft Spruce and Specialty Company**

United States

East

1-800-824-1930

(909)372-0555 (f)

900 S. Pine Hill Rd.

Griffin, Ga. 30223

West

1-800-831-2949

(770)229-2329

225 Airport Circle

Corona, Ca. 91720

Europe

UK

+44-1462-441995

+44-1462-442228

8 Cam Centre, Wilbury Way

Hitchin, Hertfordshire

England, SG4 OTW

### **Wire and Cable Sources**

Vermillion Inc

4225 W 31<sup>st</sup> Street South

PO Box 12147

Wichita, KS 67227

316-942-8238

316-942-0939

AE Petcher

817-461-9437

PIC Wire and Cable

414-246-0500